RENOVATION PLAN May 2013



KERRYHILL COURT CONDOS



Kerryhill Court \$2.6 Million Renovation Project Plan

Exterior

Windows (All Suites and Rooms)
Entrance Doors & Windows Above

Exterior Walls

Roofs

Privacy Fence

Parking Lot & Walkways

Landscaping Exterior Lighting

New Security Access System – in 25 only

Interior

Stairwell Doors and Side Panels

Stairwells Corridors

6 11 5 11 5

Suite Entry Doors

Common Rooms – Party and Fitness

New washrooms – in 27 only

New kitchens – in 27 only

New flooring and baseboards – in 27 only

Skim-coated Walls – in 27 only

Gas-fired On Demand Hot Water with Air Handler

& Related Duct Work – in 27 only

Central Split-system Coil in Air Conditioning

Air Conditioning – in 27 only

Washer/Dryer Combination – in 27 only

Mechanical & Electrical

New roof top corridor make up air units Plumbing lines inspected and serviced Main electrical distribution system thermally

scanned and serviced

Description of Exterior Renovations

Exterior Walls

- 2" Roxul Insulation
- Decorated metal siding by Garland Canada

Entrance Doors and Windows Above

- Four entrance doors: new commercial grade, clear anodized aluminum framed doors
- Side glass and windows above entrance doors: new energy efficient 1" sealed glass units

Windows (All Suites and Rooms)

New Roberge PVC slider windows with premium PVC interior sills and framing
 year warranty on window seals. 25 year warranty on framing

^{*}Reserve Fund will have \$150,000 after renovations are completed.

Roofs

- Raised roof top parapet (both buildings); new flashing
- New roof at 25 Tamarack: 3-ply roof membrane with proper sloped insulation. 10-year minimum warranty
- Restored roof at 27 Tamarack: a new restorative coating to provide better slopes to the drains and longer life expectancy. Full 10 year warranty

Parking Lot and Walkways

 Complete removal of asphalt – parking areas and walkways – and replaced with 50mm of new HL3 hot mix asphalt

Landscaping

- New permanent property identification sign (Kerryhill Court sign)
- Replacement of storm drain man holes including new covers
- 6-foot Privacy fence on the inside of front walkways blocking view of the parking lot
- Flower beds
- Common garden
- 2 new covered and screened-in permanent Gazebos
- Picnic tables
- Several new patio areas for patio furniture and picnic tables

Exterior Lighting

- Parking area lamp posts replaced energy efficient lamp posts
- New lighting bollards installed along all walkways
- Decorative landscape lighting throughout

Description of Interior Upgrades

Stairwell Doors and Side Panels

 New steel framed doors and side panels at all stairwell entrances. Ceramic glass for both doors and side panels – provides better penetration of natural light

Stairwells

- Main entrance stairwells in both buildings: new slip resistant porcelain tiles on all landings and steps
- New vinyl flooring for secondary entrance stairwells
- Painted stair railings and wall
- New energy efficient lighting
- New heaters

Corridors

- Existing ceilings replaced with new t-bar style ceiling with decorative lay-in tiles
- New energy efficient light fixtures
- All walls painted
- New decorative rubber backed carpet tile and base

Suite Entry Doors

- All suite entry doors replaced with new fire rated, insulated steel doors with new lever handles and deadbolt locks
- Door surrounds: new laminate door surrounds with suite plate and number

Laundry Rooms

- Completely renovated laundry rooms in both buildings: new ceiling, lighting, flooring, laundry
 machines (note: raised floor below new dryers for ease of access), new venting, new sinks, new
 counter area
- Drywall repaired or added to cover top of the cinder block
- Walls painted

Common Room(s)

- Existing common room in 25 Tamarack: new flooring (carpet and or laminate flooring based on buyer feedback), walls painted, new appliances and lighting, new round tables and chairs, and television and stand with cable connection
- New common room in 27 Tamarack: fitness room with equipment

Mechanical and Electrical Systems

25 Tamarack

- New roof top corridor make up air unit
- Three (3) new roof top washroom exhaust fans
- Main electrical distribution system thermally scanned and serviced. Replacement of components nearing the end of their useful life
- New security access system with card readers at both entrances
- All plumbing lines inspected and serviced

27 Tamarack

- New roof top corridor make up air unit
- Note: New roof top washroom exhaust fans were installed in 2010
- Main electrical distribution system thermally scanned and serviced. Replacement of components nearing the end of their useful life

- New washrooms in all suites complete with new sanitary drain lines and new water supply lines
- New washer and dryer
- Central air conditioning

Reserve Fund

While the intent of this renovation plan is to bring all common areas to new or like-new condition, Gallagher Property Services Inc. will contribute \$150,000 to the Condominium Reserve Fund upon completion of all renovations. This will ensure sufficient funds are available for unexpected expenses after completion of the renovations.